

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-32

Nº 2103

Date Inspected March 27-1926

House No. 309 133

Size of pipe used 6"

Was lateral at curb? yes

Was attached to main yes


Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor

Geo. Bruner



Signed

Clark Elser
Inspector for City

Filed at Engineer's Office

APR 3 1926

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2103

PERMIT TO TAP SEWER

Massillon, O., March 1st 1936

Received of Amos T. Doherty fee of \$ 2.00

for which permission is granted Charles E. Lusk

to tap East 4th sewer, on the South side

of Lusk Ave., the premises being Lot. No. 2673
St. 1312

House No. 133. Work to be done in accordance with Ordinance No. 2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Jesse Brunken