

No 2110

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Date Inspected MAR 27 1926

House No. new

Size of pipe used 6"

Was lateral at curb? see note

Was attached to main yes


Show by diagram relation of lateral to wall of building served.

If so how and location from first manhole down stream 56'-7'

Distance from first manhole up down stream to ditch at curb line and depth 50' - 6'

Name of Contractor Chas Strand

4" Lateral found 4' inside walk. Joints were bad and not wiped at time of construction some joints layed vs. grade. New pipe used Y put in Main and 6" pipe extended to house. (Y conn + 16' of 6" pipe used Extra)



Signed J. H. Maloney
Inspector for City

Filed at Engineer's Office

MAR 29 1926

Remarks _____

✓
11
13

5
1
3

16 Record

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2110

PERMIT TO TAP SEWER

Massillon, O.,

19²⁴

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 6836 779
St.

House No.

1040

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor