

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED



Nº 2122

Date Inspected April 9-1926

If so how and location from
first manhole down stream

House No. 1428

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"

Was lateral at curb? yes

Name of Contractor

Geo Brunken
East

Was attached to main

Show by diagram relation of lateral to wall of building served.

House 1428
Chas. Leindick



North

sewer

South

Signed

Clarke Elser
Inspector for City

Filed at Engineer's Office

APR 10 1926

Remarks

Repair old San. Lateral

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2122

PERMIT TO TAP SEWER

Massillon, O., April 6th 1926

Received of

J. Brumby

fee of \$

2.00

for which permission is granted

Chas. Leindecker

to tap

sanitary

sewer, on the

East

side

of

Lanton

Ave., the premises being Lot. No. 3207
St.

House No. 1422

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

J. Brumby

1:00 P.M. Friday