## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

2123

Date Inspected Mark 12-1926 House No. 1422	If so how and location from first manhole down stream
House No. /422	down stream to ditch at
Was lateral at curb?	Name of Contractor Jus Bunker
Show by diagram relation of lateral to	A STATE OF THE PROPERTY OF THE
	< 7. 2a
	eurb <12' = 3
	Hawton st
Signed Clark	Elsza Filed at Engineer's Office APR 1 3 1926
Inspector for C Remarks Repair Ja	b connect on 4" Jime

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## **Nº** 2123

## PERMIT TO TAP SEWER

	Massillon, O., Of 6 19 25
	Received of fee of \$ 2 000
for	which permission is granted Chan Linde Chan
	ap atam sewer, on the side
of	Ave., the premises being Lot. No. 3208
	St.
Но	ise No. 142 6. Work to be done in accordance with Ordinance No. 2323, duly passed
	the City Council, and Rules of the Department of Public Service.
Na	ne of Contractor