

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2133

Date Inspected APR 17 1926

House No. new car 3rd & William

Size of pipe used 6"

Was lateral at curb? yes


Was attached to main _____

If so how and location from first manhole down stream _____

Distance from first manhole down stream to ditch at curb line and depth 12' from 50' house line 7' deep.

Name of Contractor Julius Whittum

Show by diagram relation of lateral to wall of building served.



Signed J. V. Maloney
Inspector for City

Filed at Engineer's Office APR 19 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2133

PERMIT TO TAP SEWER

Massillon, O., April 14th 1919

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Seneca

Ave., the premises being Lot No.

842

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor