## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2146

Date Inspected APR 3 0 1926	If so how and location from
House No. 130 4 1110	first manhole down stream
Size of pipe used 6''	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor A B. Fisher.
Was attached to main	Name of Contractor #2
Show by diagram relation of lateral to	wall of building served.
Q. W. 777	E. OOK APR 3 0 1926
Signed Inspector for G	Filed at Engineer's Office
Remarks about 20	" fall from Bellar.

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2146

## PERMIT TO TAP SEWER

	116 110
Insp! -	Massillon, O., Cy - 12 7th 192
8 77	Received of Man 3 7 miles fee of \$ 2 "-
Friday	for which permission is granted 57 Spittle
	to tap sanday sewer, on the mode side
	of Ave., the premises being Lot. No. 2105
	House No. 1110  Work to be done in accordance with Ordinance No. 2323, duly passed
*	by the City Council, and Rules of the Department of Public Service.
	Name of Contractor M. B.