

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2148

Date Inspected April 30

House No. 830

Size of pipe used 2 in

Was lateral at curb? _____


Was attached to main _____

Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth _____

Name of Contractor Jess Brunken



Signed A. T. Boyd
Inspector for City

24 ft
Filed at Engineer's Office

4 ft → East
APR 30 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2148

PERMIT TO TAP SEWER

Massillon, O., April 30th 192

Received of Jess Brumber fee of \$ 2.00

for which permission is granted Mr Zipp

to tap Sanitary sewer, on the north side
of Cottage Ave., the premises being Lot. No. 7626
Commonwealth Ave NE 3976
St.

House No. 830. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J Brumber