FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2159

Date Inspected 5-7-26	If so how and location from first manhole down stream
House No. New	Distance from first manhole
Size of pipe used 4"	down stream to ditch at curb line and depth 263 from & Mill
Was lateral at curb? 220	Name of Contractor Earley Bura . wall of building served. A 6 Main Built previously from Mill st
Was attached to main 1/20	Name of Contractor
Show by diagram relation of lateral to	wall of building served. 6 Main Built previous
	8' Deep
Signed It Wala	WILLARD ST MAY 8 1926 Filed at Engineer's Office
Inspector for Cit	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

		to and a day	10
	Massillon, O.	, may 5 th	19_3
		V_{i}	
A second of the second	$\alpha = H$	e e e e e e e e e e e e e e e e e e e	00
Received of	e comba	fee of \$	X
Received of			
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		and the second	
or which permission is granted		and the state of t	
	1	and the second s	And the state of t
o tap	sewer, on the	and the said and a said	side
o tap	**************************************		1.5%
The total desired	A +1-0 pro	mises being Lot. No.	3659
	St.	minses being bot. 110	Ki
	50		
		11 O 11 No 2223	: 2 duly pagad
House No	one in accordance w	ith Ordinance No. 2323	o, dury passed
1.5 2. (1)			
by the City Council, and Rules of the Dep	partment of Public S	Service.	Samuel Control of the
, man (1)			18
\mathcal{H}_{\bullet}	11	and the second s	. 0
Name of Contractor		orija i satulita 🗗	n H

2159