## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2161

Date Inspected May 18 th  House No. 1559 1009  Size of pipe used 4 m	If so how and location from first manhole down stream  Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor Dess, Brunker
Was attached to main	
Show by diagram relation of lateral to	wall of building served. House
	1760
	15 storing
	1848
Alex	west of house -> South
Signed A. F. Boyd Inspector for C	Filed at Engineer's Office MAY 1 2 1926
Remarks Lateral conec	to the same of the
Remarks Lateral Conec	ced it main survivi

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2161 PERMIT TO TAP SEWER Massillon, O., 2019

				V	
Received of	. 0 03	and the second s		fee of \$_	2 Vand ware
for which permiss	$\mathcal{O}_{\mathbb{R}^n}$	Ra	74.2 4	ndr	1. ×
to tap	Commission & C	sewer,	on the	mulanda	side
of	former or many groups made	Amherst Rd	NE., the premises it.	being Lot. No.	353/z 6994+5
II N. /55	009 G Was	le to bo dono in no		linance No. 232	23 duly no

by the City Council, and Rules of the Department of Public Service.

Name of Contractor