

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5-43

Nº 2172

Date Inspected June 15/66

If so how and location from
first manhole down stream 107 ft

House No. 719

Distance from first manhole
down stream to ditch at
curb line and depth 107 ft 7 in

Size of pipe used 6

Was lateral at curb? yes

Name of Contractor _____

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

M.H.
○

North
side

Signed J. J. [Signature]
Inspector for City

Filed at Engineer's Office

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2172

PERMIT TO TAP SEWER

Massillon, O., May 18th 1919

Received of J. G. Snyder fee of \$ 2.00

for which permission is granted E. Duffenbacher

to tap sandway sewer, on the South side

of Franklin St. Ave., the premises being Lot. No. 6383
E. Snyder 14th. St.

House No. 719 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Duffenbacher