

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5-43

Nº 2173

Date Inspected _____

If so how and location from
first manhole down stream

House No. 544 734

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 8"

Was lateral at curb? yes

Name of Contractor

Was attached to main yes

Show by diagram relation of lateral to wall of building served.



Signed _____

Inspector for City

Filed at Engineer's Office

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2173

PERMIT TO TAP SEWER

Massillon, O., May 11th 1919

Received of L. G. Snyder fee of \$ 2.00

for which permission is granted E. D. Duffenbacher

to tap Sanitary sewer, on the north side

of Franklin St. Ave., the premises being Lot. No. 6496
10th St. St.

House No. 734 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Duffenbacher