FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N: 21/4				10
7 1 1			E. Curb	3.1
Date Inspected 726	If so how and location from first manhole down stream	373 ft from	1 At Hat V	Nood
House No. 8 7 4	Distance from first manhole down stream to ditch at			
Size of pipe used	curb line and depth			
Was lateral at curb? Tear, 14 a	lley	Geiger St	A	
Was attached to main / /u Main	Name of Contractor	Geiger st		
Show by diagram relation of lateral to	wall of building served.	According to the Control of the Cont		
			5	
6		energiest annes der und dem eine met gegeband (del dem eine eine eine des des eine gegeben eine gegeben der de Bestelle der dem eine der der dem eine dem eine der der dem eine dem eine der der dem eine der der dem eine de	2, 2, 2, 2, 3, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4,	
		and the second s	2 0	
	Alley	a marine minimal dis distributible secondo l'apputatione (n. 1994). La consequence (individual secondo de l'apputatione (n. 1994). La consequence (individual secondo de l'apputatione (n. 1994).	0	
Signed S. Journ	Filed at 1	Engineer's Office	5720/	26
Inspector for Cit	t y			
			,	

With

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2174

PERMIT TO TAP SEWER

Massillon, O., May 49 19-
Received of A Machine fee of \$2
for which permission is granted ABMACCE
to tap sewer, on the side
of Ave., the premises being Lot. No. 4704 St.
House No. 2323, duly passed 629
by the City Council, and Rules of the Department of Public Service.
Name of Contractor