

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2179

Date Inspected June 2

If so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 in


Was lateral at curb? yes

Name of Contractor

Dan. Tobin

Was attached to main

Show by diagram relation of lateral to wall of building served.



50 ft-Pipe
7 ft-D

Signed

A. T. Boyd

Inspector for City

Filed at Engineer's Office

JUN 2 1926

Remarks

Lateral connected to lateral at curb 182 ft 4 1/2 th from man
hole at miller ave

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2179

PERMIT TO TAP SEWER

Massillon, O.,

May 24th 1926

Received of

fee of \$ 2.00

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 2725
St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor