FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N	ļ	() () ()	9	1	86
ΤA			<i>-</i> €	ı	ou

	하는 사람들은 사람들이 되었다. 그는 사람들은 사람들이 함께 되었다. 그 사람들이 되었다. 그 사람들이 되었다. 생물을 보고 있는 것이 되었다. 그는 사람들이 되었다. 그 사람들이 되었다. 그는 사람들이 되었다. 그는 사람들이 되었다.
Date Inspected June 8 th	If so how and location from first manhole down stream
House No. New	Distance from first manhole
Size of pipe used 4 six	down stream to ditch at curb line and depth
Was lateral at curb? No	
	Name of Contractor & Dieffenbacher
Was attached to main	
Show by diagram relation of lateral to	wall of building served.
	The state of the s
entengen vita man value un järjällija all til mit vit vit järjällijä all til mit vit vit järjällijä all til mi	Main Dewer & Sinsoln, aug North
	- 7/10-00j-
- 1985년 - 1985년 1985 - 1985년 - 1985년 1985	Hruse
	To the state of th
있는 경기에 가는 전 시험에 가는 것이 하지 않는 것이 되는 것으로 한다. 	3 6/20- Pipe
	20 1740
$\Lambda = \Lambda = \Lambda$	A Committee of the comm
Signed A. J. Boyd	Filed at Engineer's Office 111N 9 1926
Dinspector for C	
Pamarka Lateral Commerce	ted to sewer in alley on strit-line from

Tovate NoRecord

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

vo 2186 PE

PERMIT TO TAP SEWER

	Massillo	n, O.,	les .
Received of		fee of \$	
for which permission is gra	4 4	The service	
to tap		e sic	de
	15 M	e premises being Lot. No. 24 17 7	/
House No.	Work to be done in accordance	ce with Ordinance No. 2323, duly pass	ed
by the City Council, and R	ules of the Department of Pub	olic Service.	
Name of Contractor	Alechander		