

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2187

7
5/13
✓

Date Inspected June 5. 1926

If so how and location from first manhole down stream _____

House No. Lot 70.

Distance from first manhole down stream to ditch at curb line and depth Sewer in back yard - The House

Size of pipe used 6 inch


Was lateral at curb? _____

Name of Contractor Chas. Stroud

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

4 feet 6 inches
from North
East corner
of the Building
2-0. feet deep.



Signed Wm. Deshry
Inspector for City

Filed at Engineer's Office JUN 16 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2187

PERMIT TO TAP SEWER

Massillon, O., June 5th 1926

Received of Chas. Stroud fee of \$ 2.00

for which permission is granted Maggie

to tap Sanitary sewer, on the west side

of 9 Lawrence Ave., the premises being Lot. No. 70
St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chas. Stroud