

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2189



Date Inspected June 15/26

If so how and location from
first manhole down stream

91 ft

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

91 ft 7 ft.

Size of pipe used 6"

Was lateral at curb? yes

Name of Contractor

Eastman

Was attached to main yes

Show by diagram relation of lateral to wall of building served.



Signed J. Farmer
Inspector for City

Filed at Engineer's Office

JUN 16 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No 2189

Massillon, O.,

1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor