FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2190

Date Inspected	If so how and location from first manhole down stream
House No.	Distance from first manhole
. 64	down stream to ditch at
Size of pipe used	curb line and depth
Was lateral at curb?	and the second of the second o
	Name of Contractor A on the contractor
Was attached to main	1101110 01 0011111111111111111111111111
Show by diagram relation of lateral to	wall of building served.
	1 AND The
	With the second of the second
	and the second s
Signed	Filed at Engineer's Office JUN 1 6 1926
Inspector for C	
Remarks	

The state of the s

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N_{\bullet} 2190

PERMIT TO TAP SEWER

	Massillon, O.,	A Company of the Comp	1/
Received of 24	etetten C.	∯ fee of \$_	202
for which permission is granted	1 of mate	A.	C.
and the second s	sewer, on the		side
of Malter	Ave., the premises	being Lot. No.	10363

House No. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Bearing and Sand Sunday sugar