FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2192

SE-173

Date Inspected				
House No. 7 4/	Distance from first r down stream to ditcl curb line and depth	nat 🍠 🗸 🖓 💮	717 de	
Was lateral at curb? Was attached to main	Name of Contractor	Basilin.	<u> </u>	·
Show by diagram relation of lateral to	wall of building serve	d.	La magna e d .	
3+28/-	alanda anaka mana mana mana mana mana mana ma			
Signed	<i>Nazye</i> (1907)	Filed at Engineer's Office	. JUN 1 6	
Inspector for Circles Remarks	ty			

18 18 CO

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2192

PERMIT TO TAP SEWER

Massillon, O., 1926
Received of 19 1 14 the fee of \$ 200
Received of
for which permission is granted 6 1 2/2 tutte.
for which permission is granted
to tap sewer, on the side
ofAve., the premises being Lot. No. 6480 St.
730 House No. Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.
Name of Contractor