## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

SE-173

Nº 2193

Signed Inspector for Cit	JUN 1 6 1926  Filed at Engineer's Office			
10 6 2 15 5				
Show by diagram relation of lateral to	wall of building served.			
Was lateral at curb?  Was attached to main	Name of Contractor			
House No. Z	Distance from first manhole down stream to ditch at curb line and depth			
Date Inspected	If so how and location from first manhole down stream			

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2193 PERMIT TO TAP SEWER

		Massillon, O.,	<u>James 2.</u>	res Assemi P	19
Received of	191.7	Min	fee of	\$	
or which permission is gra					6
o tap San				4 - 1	side
of	4	Ave., the prem	ises being Lot. I	No. / //	25
742 House No.	Work to be done in		1 Ordinance No.	2323, duly	passed
by the City Council, and Ru	ales of the Departme	nt of Public Se	rvice.		
Name of Contractor 2	- titte		and state of		3 A