

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5-43

Nº 2195

Date Inspected _____

House No. 743 _____

Size of pipe used _____

Was lateral at curb? _____

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream 200 ft _____

Distance from first manhole
down stream to ditch at
curb line and depth 200 _____

Name of Contractor _____

Signed G. Elmer _____

Inspector for City

Filed at Engineer's Office

JUN 16 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2195

PERMIT TO TAP SEWER

Massillon, O.,

June 7th 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor