Nº 2202

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected June 10 th	If so how and location from first manhole down stream
House No.	Distance from first manhole down stream to ditch at
Size of pipe used 6 m	curb line and depth
Was lateral at curb? No-	\mathcal{R}
Was attached to main	Name of Contractor & Chile
Show by diagram relation of lateral to	wall of building served.
	1 OK
	Demo
the state of the s	
Punhing	
Signed A T. Boyd Station Inspector for City	Filed at Engineer's Office JUN 1 7 1926
Inspector for City	y
Remarks Lateral Connected	- at-man hale runing 107 ft- to house in
	alles

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

740	~~~~		•			111
			Massillo	on, O.,	~10	19 34
Re	ceived of P	Bui	Ref		fee of \$	
for which	n permission is gra	anted M7	11/40	noin		·
to tap	<u> </u>	Manufacture of	sewer, on th	1e //		side
of	mante.	27	Ave., th St.	he premises being	Lot. No. 46	- Andrews
House N	ю	Work to be de	one in accordar	nce with Ordinanc	e No. 2323, duly	passed
by the C	ity Council, and R	tules of the Dep	partment of Pu	ıblic Service.		

2202

NO