

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2206

Date Inspected 6-11-26

If so how and location from
first manhole down stream _____

House No. 1115

Distance from first manhole
down stream to ditch at
curb line and depth _____


Size of pipe used 6"

Was lateral at curb? yes

Name of Contractor _____

Was attached to main _____

Show by diagram relation of lateral to wall of building served.



Signed _____

E. B. Coffin
Inspector for City

Filed at Engineer's Office _____

JUL 13 1926

Remarks _____

Lateral was laid when main sewer was built.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2206

PERMIT TO TAP SEWER

Massillon, O.,

January 11, 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 2577
St.

House No.

1115. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor