Nº 2213

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Juni 15:1926	If so how and location from first manhole down stream
House No. 2/02. 200 160	Distance from first manhole
Size of pipe used	down stream to ditch at curb line and depth 27/2 cut par Manuschen Stand Month
Was lateral at curb?	
Was attached to main year	Name of Contractor Shas, Itered
Show by diagram relation of lateral to	wall of building served.
4.0 fut from 90 comments Main Curt	reth Hest
cornethe Mount Russ	William 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
a Rut Buch	
Die Jack and	
	(rever
Signed 2m. Lush	Filed at Engineer's Office JUN 1 6 1926
Inspector for Cit	
Remarks	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER Massillon, O., 1926 for which permission is granted sewer, on the Ave., the premises being Lot. No. / 6 0 St.

House No. 2100. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

a gitting at war in to a file it is it is