

Nº 2214

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-30

Date Inspected JUN 17 1926

House No. New 823

Size of pipe used 6"

Was lateral at curb? yes


Was attached to main

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth 224' - 6'

Name of Contractor J. Wittman

Show by diagram relation of lateral to wall of building served.



Signed J. H. Maloney
Inspector for City

Filed at Engineer's Office

JUN 21 1926

Remarks This lateral was not extended under walk as usually the case of others on this same street.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2214

PERMIT TO TAP SEWER

Massillon, O.,

June 14th 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

823

4005

St.

House No.

1319

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor