

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2217

Date Inspected June 17th

House No. 600

Size of pipe used 6 in

Was lateral at curb? yes


Was attached to main

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor Julius Wiltman

Show by diagram relation of lateral to wall of building served.



Signed A. F. Boyd
Inspector for City

Filed at Engineer's Office **JUN 18 1926**

Remarks Lateral connected to lateral on Summit St 5 1/2 ft South from straight line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2217

PERMIT TO TAP SEWER

Massillon, O.,

June 16th 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot No.

4th ST SW

St.

House No.

600. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor