



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2218

Date Inspected June 17th

If so how and location from
first manhole down stream _____

House No. 609

Distance from first manhole
down stream to ditch at
curb line and depth _____


Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor Julius Wittman

Was attached to main _____

Show by diagram relation of lateral to wall of building served.



Signed A. F. Boyd
Inspector for City

Filed at Engineer's Office Summit St -> North

JUN 18 1926

Remarks Lateral connected to lateral at curb 4 1/2 ft from street line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2218

PERMIT TO TAP SEWER

Massillon, O.,

June 10th 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 667
St.

House No. 604

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor