

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2220

Date Inspected 6/18/26

If so how and location from
first manhole down stream _____

House No. 1120

Distance from first manhole
down stream to ditch at
curb line and depth _____

Size of pipe used 6"

Was lateral at curb? yes

Name of Contractor _____

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

Signed _____

Frank B. Jones
Inspector for City

Filed at Engineer's Office _____

JUN 21 1926

Remarks _____

A. H.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2220

PERMIT TO TAP SEWER

Massillon, O., June 15th 1926

Received of J. Wittmann fee of \$ 2.00

for which permission is granted John Company

to tap sand clay sewer, on the East side

of Young Ave., the premises being Lot. No. 2576
St.

House No. 1120. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J. Wittmann