FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	Nº 2221	AND SIGNED WHEN RETURNED
	Date Inspected	6 If so how and location from first manhole down stream.
	House No Jat 676	Distance from first manhole down stream to ditch at
-	Size of pipe used	curb line and depth
	Was lateral at curb? Was attached to main	Name of Contractor Allman
	Show by diagram relation of lateral	to wall of building served.
	entre de la companya	

		aus in the contract of	ere Car		
		.,4	•		
	May 1	1			
Signed Film	el 10 str	nel	Filed at Engi	neer's Office	UN 2 1 1926
Signed	Inspector for City			ileer's Office	
	161				

Remarks Off

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2221

PERMIT TO TAP SEWER

		Massillon, O	, June 18th	1926
Received of	1 Ana	reconstruction of	fee of \$	02
	on is granted Co			
	and and	Strain a market	last	side
· Jan	and the second s	Ave., the pr	emises being Lot. No.	76
4th	ST SW	St.		

Name of Contractor A Management

by the City Council, and Rules of the Department of Public Service.