

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2222

Date Inspected 6/18/26

House No. 601 405

Size of pipe used 6"

Was lateral at curb? yes.

Was attached to main

Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor

Signed Frank B Jones
Inspector for City

Filed at Engineer's Office JUN 21 1926

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2222

PERMIT TO TAP SEWER

Massillon, O.,

June 18th 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

405

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor