FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND RECORD

Nº 2226

and the control of th	。 · · · · · · · · · · · · · · · · · · ·			
Date Inspected 22	If so how and location from first manhole down stream			
House No. New	Distance from first manhole			
Size of pipe used 4 in	down stream to ditch at curb line and depth			
Was lateral at curb? No				
Was attached to main	Name of Contractor & Brunker			
Show by diagram relation of lateral to	wall of building served.			
	3			
	5-410			
	2011 vipe			
	3 room = Rose. St			
Signed A & Boyd	Filed at Engineer's Office JUN 2 3 1926			
Inspector for C	ity			
Remarks Lateral Connec	ted to main 5% It at curb from strict			

9

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2226

PERMIT TO TAP SEWER

		Massillon, O.	, Jahrenson	212/1926
Received of	1. Bonn	hander .	fee o	000_
or which permissio	n is granted	· Me	Literatura	. DK
o tap	Carrier of Section 1	ewer, on the		side
of R		Ave., the pre	2885 emises being Lot.	No. 041466
House No. 316			ith Ordinance No.	2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor