## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2228

\_\_\_\_\_

Date Inspected Jan 8	If so how and location from first manhole down stream
House No. 706	Distance from first manhole
Size of pipe used & in	down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor G. Early
Show by diagram relation of lateral to	wall of building served
Show by diagram relation of lateral to	The state of building served.
	50 ft-Pipe
	North a man sever
	Pigeon run Road
Signed A & Boyd	Filed at Engineer's Office JAN 1 0 1927
Inspector for Ci	ty operation of the state of th
Remarks Lateral come	cled to lateral at curb 98 ft from Man

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2228

## PERMIT TO TAP SEWER

		Massillon, O.,	Jane Laborer	22 1926
		2 2 d d a -		
to tap	st sw Son Road	sewer, on theAve., the pren	Eas +	side O.L. 274 o.
House No. 706	Work to be	done in accordance wit	h Ordinance No. 2	323, duly passed
11.04.50 1101.14				
by the City Council	, and Rules of the De	epartment of Public Se	rvice.	
Name of Contractor	r Laly.		Z, reducido.	