

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2230

✓
11
51

Date Inspected June 24th

If so how and location from
first manhole down stream.....

House No. 402

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 in


Was lateral at curb? No

Name of Contractor

J. Bunker

Was attached to main.....

Show by diagram relation of lateral to wall of building served.



Signed

A. T. Boyd

Inspector for City

Filed at Engineer's Office

JUN 25 1926

Remarks

Lateral connected to main 9 ft from street line on
House

110 Record of
Chester R. E.
Jm. Jones, from
2307, 1907.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2230

PERMIT TO TAP SEWER

Massillon, O.,

June 22nd 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor