FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2234

| | Date Inspected July 1 th | If so how and location from first manhole down stream |
|----|--|--|
| | House No. New | Distance from first manhole down stream to ditch at |
| | Size of pipe used 6 xm | curb line and depth |
| | Was lateral at curb? | 10 6 |
| | Was attached to main | Name of Contractor M. E. Lumbach |
| | Show by diagram relation of lateral to | wall of building served. |
| | | 1648 |
| | | 44 ft Pape |
| | | Mai Souls |
| | tig 1 de 1 d | and the state of t |
| | -1.00M | Medill and |
| | Signed A. T. Boyd Inspector for City | Filed at Engineer's Office JUL 2 1926 |
| ļ. | Remarks Lateral Course | ted to lateral at curb 95 ft from strant |
| | | li Harrel |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2234 PERMIT TO TAP SEWER

| | Massillon, O., A. 26 | 1926 |
|--|---|----------|
| Received of | fee of \$ 2 ° | 1/ |
| for which permission is granted | 10 Line de la | |
| to tap the land | sewer, on the | side |
| of had Af | Ave., the premises being Lot. No. 23/ | 3 |
| House No. /2/2 Work to be | done in accordance with Ordinance No. 2323, duly | passed |
| by the City Council, and Rules of the Do | epartment of Public Service. | |

Name of Contractor....