FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2237

Date Inspected June 30 th	If so how and location from first manhole down stream
House No. 505	Distance from first manhole
Size of pipe used 4 m	down stream to ditch at curb line and depth
Was lateral at curb? Na	
Was attached to main	Name of Contractor & Brunker
Show by diagram relation of lateral to wall of building served.	
	644-\$
na na visti saje i sadi diegodinek jesti si. Si	20 ft-Pipe
Heli (1918-14) o mondina di silino d	Main · sever 7 ft-9
	Schrock: are -> North
Signed A. F. Baya	Filed at Engineer's Office JUL 1 1926
2 Inspector to City	
Remarks fateral connected to main 13 1/2 from strait line on House	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Received of Brunker fee of \$ 200

for which permission is granted Mr. Berry

to tap Sanitary sewer, on the side

Schrock Ave., the premises being Lot. No.

House No. 323 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J Brunker