FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

		-	2	. A	~
	34.	• 4	9 8	/8	
		_	┏.	4	R B

No

		41-7 1-7-2	
Date Inspected July 8th	If so how and location from first manhole down stream		
House No. New 432	Distance from first manhole		
Size of pipe used 6 m	down stream to ditch at curb line and depth		
Was lateral at curb?	Name of Contractor & While	tman	
Was attached to main	-		
Show by diagram relation of lateral t	o wall of building served.		
	16/1-		
	100	1-0:11	×
	$\beta z_{\mathcal{F}}$	- Organ	v
	S. St.	g i	
		.	
•	O Main Scur	s a successión - monte experiencia de septembre de commencia de productivo de section de la commencia de la co	
mes/ «	- 101/2 for st-		
d OB	Filed at Engineer's	Office JUI 9 1	926
Signed T. Boyd Inspector for	City		3
La trades	cted to lateral at en	1 20 ft from	strait-
Kemarks			42400
		none ou	110

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2246

PERMIT TO TAP SEWER

Massillon, O., 7 Th. 1926
Received of Attaches fee of \$ 200
for which permission is granted Cala Cala
which permission is granted
to tapsewer, on theside
of
5
432
House No. Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.
Name of Contractor Walter Commen