FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2247

and the state of t	ekko ekki 170 ali
Date Inspected July 14	If so how and location from first manhole down stream
House No. New	Distance from first manhole
Size of pipe used 6 m	down stream to ditch at curb line and depth
Was lateral at curb? No	
Was attached to main	Name of Contractor Dan Folin
Show by diagram relation of lateral to	wall of building served. House
	104 ft-Pipe
	849
	Kephler St - North
Signed A. J. Boyd Inspector for Cit	Filod at Engineer's Office
Remarks Lateral Com	ected to short sever runing from Pearl

1/2 Record

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2247

Name of Contractor

PERMIT TO TAP SEWER

710
Massillon, O., July 8 1926
Q - T-1-10 / 20
for which permission is granted H Plankett
S contract of the side
of Heppel Lot. No. Ave., the premises being Lot. No. 244
St. 3846
House No. 1517 Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.