FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2249

	그 하님 중에 만든 맛을 봤는데 맛이 하는데 그리고 있다. 그 모습	
	Date Inspected Auly 9 th	If so how and location from first manhole down stream
	House No.	Distance from first manhole down stream to ditch at
	Size of pipe used 4 in	curb line and depth
	Was lateral at curb?	Name of Contractor Chas Strond
	Was attached to main	
	Show by diagram relation of lateral to	wall of building served.
		77/-0
		132 fl Pipe
ita .	Allegand artes makes participated	Main Main and Marin and Ma
	Signed A-97 Boyd Inspector for C	- Rolch St. Filed at Engineer's Office JUL 1 0 1926
	Remarks Sateral Connection	cted to lateral at curb 4 ft from strail
	Kemarks	11.80

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2249

3.

PERMIT TO TAP SEWER

				Ŋ	Iassillon, O)., <u>J</u>	ly 9	, u	1926
	Received of	Cla		L	gangara d	0	fee of	\$ 2	ر ب
	nich permission	is granted	e.	7 8	10	m. A	es	<u>*</u>	
to tap	da	ila	+7		, on the	, and the second		4	side
of	(R)	t.L			Ave., the proof.	emises bei	ng Lot. N	Io	764

House No. Signature Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chas Atom d

60 m/c