

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-10

Nº 2262

926182 700

Date Inspected _____

House No. New 411

Size of pipe used 4"

Was lateral at curb? yes


Was attached to main _____

Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth 80' - 6"

Name of Contractor Jess Brunker



Signed J. S. Malone Filed at Engineer's Office _____

Inspector for City

Remarks about 5' fall to end of Lateral at cur.
from cellar floor.

JUL 28 1926

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2262

PERMIT TO TAP SEWER

Massillon, O.,

July 26 1924

Received of

Jess Bruncker

fee of \$

2.00

for which permission is granted

same

to tap

Sanitary

sewer, on the

South

side

of

Korman Blvd

Ave.,
St.

the premises being Lot. No.

7007

3544

411

House No.

3544

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Jess Bruncker