FOLLOWING DATA TO BE ANSWERED BY INSPECTOR NED WHEN DETIIDNED

Nº 2269	AND SIGNED WHEN RETURNED	
Date Inspected august	If so how and location from first manhole down stream	
House No. 839 Size of pipe used 6 and	Distance from this manner	
Was lateral at curb?		
Was attached to mainShow by diagram relation	of lateral to wall of building served. w. East oak st s. s.	
	1-13. 3/2	events.
	HOUSE	

Filed at Engineer's Office Signed

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER 2269 Received of for which permission is grante Ave., the premises being Lot. No. 954 St. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor...

San Alexander

ŧ