

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2275

4-18

Date Inspected August 10-1926 If so how and location from
first manhole down stream _____


House No. Lot 4047 220 Distance from first manhole
down stream to ditch at _____

Size of pipe used 6" curb line and depth _____

Was lateral at curb? yes Name of Contractor Jes Bunker

Was attached to main _____

Show by diagram relation of lateral to wall of building served.



Signed Clark Elser Inspector for City Filed at Engineer's Office AUG 11 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2275

PERMIT TO TAP SEWER

Massillon, O., 7/7 19

Received of

Brunken & Weston

fee of \$

22

for which permission is granted

W. Eisenbraun

to tap

Sanitary

sewer, on the

North

side

7793

of

Korman Blvd.

Ave., the premises being Lot. No.

4047

St.

House No. 220

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Brunken & Weston