## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 2280	AND SIGNED	WHEN R	RETURNED	
147 12 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			9)4	an and a second
Date Inspected 8-/3-26	If so how and location from first manhole down stream			
House No. # 850 Size of pipe used 6"V.5.P.	Distance from first manhole down stream to ditch at curb line and depth		Cs.	
Was lateral at curb? No Curb-but	Vateral was to curb line  Name of Contractor		Geo. Early	· /
Was attached to mainShow by diagram relation of lateral to	wall of building served.	· · · · · · · · · · · · · · · · · · ·	50,	18" Below top of find.
SHOW By diagram relation of lateral to		#850	255	clean out Plug 4"VSP from the into house the
The second second	4/	HULL PORCH	32	62° of 6" V.S.P.

Filed at Engineer's Office Signed Inspector for City no. Oakum used at joints

Remarks

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2280

## PERMIT TO TAP SEWER

			//
	Massillon, O.,	au 912	1926
		l l	
of the second se	<b>^</b>		A ( ! !)
Received of	and the second	fee of \$	
Received of		ΙΕΕ ΟΙ φ	
	7	$\mathcal{L} = \mathcal{D} \prod_{i \in \mathcal{L}} \mathcal{L}$	
for which permission is granted have	han col	- LLS Combe	
for which permission is granted	. //	٠	
		and the second	
to tap and and s	ewer on the	month	side
to tap	cvci, on the		
of the Chief	Ave the premi	ses being Lot No	1462
	St.	· * *	
	St.		
The second secon			
House No. Work to be done	in accordance with	Ordinance No. 2323	, duly passed
			· **
by the City Council, and Rules of the Depart	ment of Public Ser	vice.	
10000			
the state of the s			
Name of Contractor	<del></del>	Salah Barangan	