FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2282	AND SIGNED WHEN RETURNED	mandradure.
	요요요하다	
Date Inspected 8-19-26	If so how and location from first manhole down stream	
Iouse No. 324	Distance from first manhole	
Size of pipe used 4" V.S.P.	down stream to ditch at curb line and depth	
Was lateral at curb? No	Name of Contractor Jess Brunker	s peul
Was attached to main	Name of Contractor	
Show by diagram relation of lateral to	wall of building served.	5 Sidewalk
	Management of the second of th	a <u>n anna an an daoine an an an an an an</u>
	1000	10000 Courb
	So about 6' Deep 2?	6 Deep of curb
	43'-4"V5P. 43'-50" Son	itary Sewer
grade production of the second	CHESTNUT S	5T

Signed Leo. C. Wallace Filed at Engineer's Office Inspector for City

Remarks

No Oakum used at joints

AUG 1 9 1926

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2282

PERMIT TO TAP SEWER

		Massillon, O.,	, 8/17		19
Received of	Brunk	wo of fresh			
or which permission i	is granted C	Sinderla	<u> </u>		
o tap		sewer, on the	Verth	201	side
of Chisme	at lit	Ave., the pre St.	mises being Lo	ot. No	
House No. 342	Work to be do	one in accordance wi	th Ordinance 1	No. 2323, duly	y passed
oy the City Council, a	nd Rules of the Der	partment of Public S	ervice.		
	at and	A. S. S. S.			