FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 2287	AND SIGNED WHEN RETURNED
그렇게 살았다면 하는 하는 것이다.	선생님의 사람들이 되는 것이 없는 생활이 되었다.
Pate Inspected 8/24/26	If so how and location from first manhole down stream
House No. A West Cherny Size of pipe used 6"V. S.P.	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb? Yes	Name of Contractor Geo. Early
Was attached to main	o wall of building served. K. Sever
Show by diagram relation of lateral to	y wan or building serve
	Grade 0.57 4' Below & Coro
	EURB /
	6"VS? 1 section of 1 Sinitary Sewer VS. WEST CHERRY ST. W
Signed Leo. C. Walla	Filed at Engineer's Office 8/z 4/z6
- Inchector for t	City 1" V.S.P. to allow pipe to go under find.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2287

PERMIT TO TAP SEWER

					Service of the servic		- B	
				Massillon, O	., a-	723		19
Receive	ad of	111	Q.E.	and the second s	•			
for which peri		is oranted	\mathcal{H}		24	The state of the s	*	
			źsew		1		45	a Jakoba
of	L	my f	/sew	Ave., the pro-		ng Lot. No)	side
		ట్		St.				en far
House No		Worl	t to be done in	accordance w	ith Ordina	nce No. 2	323, duly	passed
by the City C	council, a	nd Rules o	f the Departme	ent of Public S	Service.			
Name of Con	tractor	Hant &	Commence of the second			The second secon		