FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2288

Date Inspected $\frac{8/24/26}{727}$	If so how and location from first manhole down stream 232	
House No. (New) 121 Size of pipe used 6"	Distance from first manhole down stream to ditch at	
Was lateral at curb? No. Was attached to main Yes	Name of Contractor Chas. Straud	
Show by diagram relation of lateral to	wall of building served.	1
	~12.5 × 11.5>	Z.
	*	
Signed Harry M. Pip.	Filed at Engineer's Office	s St. Main
Inspector for Cit		2 5 1926

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2288

PERMIT TO TAP SEWER

	Massillon, O.,	and the state of t	19
Received of	en e		00
		r th	<u>. #8</u>
for which permission is granted		A Secretary Assessment	
to tapse	wer on the	A your rolling	side
of hall in	Ave., the premise	s being Lot. No.	5243 260
House No. 727 Work to be done i	n accordance with O	Ordinance No. 2323,	duly passed
by the City Council, and Rules of the Departm	nent of Public Servic	ce.	
Name of Contractor			
•			