## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| No    | 2291     |  |
|-------|----------|--|
|       | 224I     |  |
| T.4 • | M W U IL |  |

| Pate Inspected 8/15/26  House No. (New)  Size of pipe used 6" | If so how and location from first manhole down stream  Distance from first manhole down stream to ditch at curb line and depth |        |
|---|--|--------|
| Was lateral at curb? <u>Ve S</u>                              | Name of Contractor Chas.   | Straud |
| Was attached to main  | · · · · · · · · · · · · · · · · · · ·  |        |

Show by diagram relation of lateral to wall of building served. Signed

Inspector for City

Filed at Engineer's Office

Remarks

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## No 2291 PERMIT TO TAP SEWER

|  | Massillon, O     | " hing       | Market G    | <u> </u>   | _19×                                  |
|--|------------------|--------------|-------------|------------|---------------------------------------|
| Received of  | ones de          |              | fee of \$_  |            | <u> </u>                              |
| which permission is granted  |                  |              |             |            | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| tapsew   |                  |              | 1           |            | side                                  |
| me delle !   | Ave., the prost. | emises being | g Lot. No.  | 145        | 15                                    |
| ouse No Work to be done in   | accordance w     | rith Ordinar | ice No. 232 | 23, duly   | y passec                              |
| the City Council, and Rules of the Departme  |                  |              |             | * 1 .<br>* | W. Tracking                           |
| water to be the state of the st | ng r             |              |             |            |                                       |