FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	ann Anna Cheanacha
Date Inspected Aug 26	If so how and location from first manhole down stream
House No. New	Distance from first manhole
Size of pipe used & in	down stream to ditch at curb line and depth
Was lateral at curb? No	News of Contractor & A Hand tatter
Was attached to main yes	Name of Contractor & Hoestetter
Show by diagram relation of later	al to wall of building served.
	ar to wan or building served.
Parada da parada da menderal da periodo de la composição de la composição de la composição de la composição de Composição de la composição de	95 H- Pike
	W Main sewer 13 sift from man Hole
ing the state of t	Campbell and
Signed A. J. Boyd Inspector	Filed at Engineer's Office AUG 2 7 1926
Remarks Lateral Ca	meded to main 24 ft from Strait line on

No

2296

Rund

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2296

PERMIT TO TAP SEWER

	Massillon, O., ang 2 4th 1926
	V San
Received of	the p fee of \$2
for which permission is granted	Dentatus Corps
de de de	er, on theside
to tap sew	Ave., the premises being Lot. No. 6451
of Carry	St.
House No. 1522 Work to be done in	accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor