FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

No			22	99
----	--	--	----	----

Date Inspected Aug 26 House No. 9/6 920	If so how and location from first manhole down stream	
House No. 9/6 920	Distance from first manhole	- -
Size of pipe used & Management	down stream to ditch at curb line and depth	-
Was lateral at curb?	Name of Contractor M Lembach	
Was attached to main	Name of Contractor III Lindall	
Show by diagram relation of lateral to	wall of building served.	
	44 ft-Pipe	
	Main Dewer	
	Euclid and -> &	
Signed A. J. Boyd Inspector for Cit	Filed at Engineer's Office AUG 3 0 1926 ecled to lateral at care 13 ft from	
Remarks Sateral comme	ected to lateral at curt 13 ft from	
	Stril-line on How	isl

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Nº 2299	
	Massillon, O., Cener 26 1926
ani	
Received of	Line of the or
or which permission is granted	1 AD Paul
o tap	sewer, on the side
of Eucl	Ave., the premises being Lot. No. 80/3264
920 9/6. Wo	ork to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor