

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No 2314

3-28

Date Inspected _____

If so how and location from
first manhole down stream _____

House No. 450

Distance from first manhole
down stream to ditch at
curb line and depth _____

Size of pipe used _____

Was lateral at curb? _____

Name of Contractor _____

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

Signed _____

Inspector for City

Filed at Engineer's Office

OCT 2 1926

Remarks

*Lateral put in by Wendell C. without notice for
this. This was used without advised of the use of his name in the
out project. Reported 9-30-26 by William to C.E. Rife*

