FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 6 - 13Date Inspected If so how and location from first manhole down stream... House No. Distance from first manhole down stream to ditch at Size of pipe used. curb line and depth Was lateral at curb? Name of Contracto Was attached to main ______ Show by diagram relation of lateral to wall of building served. Filed at Engineer's Office... Inspector for City

Remarks

SOTOGRANI VS GENEVANA BELOT ATAM DIVINOLOGY GENEVAR MERW GENERA OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

DEDMIT TO TAD SEWER

N9 2316	itani ing palamati.		beinespent eist
olotium in i			<u>9/7</u>
Received of			fee, of \$ 22
or which permission is grai			<u>6 er bodonste savio</u> 92 gotto:4
o tap Sani- of Jac (<se< td=""><td>tary sewe n St</td><td>r, on the $\stackrel{ extstyle V}{=}$ Ave., the premises</td><td>V 251 4551 being Lot. No. 134</td></se<>	tary sewe n St	r, on the $\stackrel{ extstyle V}{=}$ Ave., the premises	V 251 4551 being Lot. No. 134
			linance No. 2323, duly r

House No. 1 2 7 Work to be done in accordance with ordinance 113, 223, 223, p

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Linkore