

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2322

Date Inspected Sept 14

If so how and location from
first manhole down stream.

House No. New

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 4 in

Was lateral at curb? yes

Name of Contractor Jess. Bunker

Was attached to main

Show by diagram relation of lateral to wall of building served.



Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office

SEP 15 1926

Remarks Lateral connected to lateral 15 ft from street line on House

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2322

PERMIT TO TAP SEWER

Massillon, O., Sept 10th 1919

Received of Jess Brunker fee of \$ 2.00

for which permission is granted Jame

to tap Sanitary sewer, on the West

of So. Erie Ave., the premises being Lot. No. 350
St.

House No. None Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Jess Brunker